


The Trail Inventory of North Attleboro NFH North Attleboro, MA



Prepared By:
Federal Highway Administration
Central Federal Lands Highway Division
March, 2012



TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
I. <u>TRAIL AND TRAIL FEATURE SUMMARIES</u>	1 - 1
II. <u>TRAIL LOCATION MAPS</u>	2 - 1
III. <u>TRAIL IDENTIFICATION LIST</u>	3 - 1
IV. <u>TRAIL CONDITION RATING SHEETS</u>	4 - 1
V. <u>TRAIL DEFICIENCY RATING SHEETS</u>	5 - 1
VI. <u>PHOTOGRAPHIC SHEETS</u>	6 - 1
VII. <u>GLOSSARY</u>	i

North Attleboro NFH

Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

Trail Surface Type	Excellent		Good		Total
	Miles	%	Miles	%	Miles
Native	0.41	55%	0.33	45%	0.74
Total	0.41	55%	0.33	45%	0.74

Trail Miles and Percentages by Trail Classification and Condition

Trail Classification	Excellent		Good		Total
	Miles	%	Miles	%	Miles
TC2	0.41	55%	0.33	45%	0.74
Total	0.41	55%	0.33	45%	0.74

*Admin Roads are included in the inventory but are not rated for condition.

Trail Features



Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T200	Sign	1	No	0.00	NOAT_C2_0004
T200	Trailhead	1	No	0.00	NOAT_C2_0005
T200	Puncheon -lf	25	No	0.03	NOAT_C2_0007
T200	Sign	1	No	0.17	NOAT_C2_0009
T200	Step: Log -each	39	No	0.18	
T200	Sign	1	No	0.33	NOAT_C2_0011
T200	Begin Section	1	No	0.33	NOAT_C2_0012
T200	Bench	1	No	0.34	
T200	Bridge -sf	126	No	0.34	NOAT_C2_0013
T200	Begin Section	1	No	0.41	NOAT_C2_0015
T200	Step: Log -each	29	No	0.43	
T200	Crib: Log -cf	44	No	0.63	
T200	Sign	1	No	0.70	NOAT_C2_0019
T200	Sign	1	No	0.71	NOAT_C2_0020
T200	Bridge -sf	198	No	0.73	NOAT_C2_0021
T200	Sign	1	No	0.73	NOAT_C2_0002

sf - square feet

lf - linear feet

cf - cubic feet

North Attleboro NFH Trail Location Map




Trails ID

Station Name: North Attleboro NFH

Org Code: 53270

Trail Number	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T200	Nature Trail	Native	10023341	0.74	From North of Hatchery Office to End of loop

TRAIL CONDITION



Trail Name: Nature Trail
Trail Number: T200

Refuge Name: North Attleboro NFH
Region: 5


Total Length: 0.74 Miles

Section Number	001	002	003
Section Length (miles)	0.33	0.08	0.33
SAMMS Number	10023341	10023341	10023341
Rating Date	07/28/2006	07/28/2006	07/28/2006
Trail Section Information			
Trail Class	TC2	TC2	TC2
Surface Type	Native	Native	Native
Surface Firmness	Firm	Firm	Firm
Width (inches)	24	44	24
Average Grade (%)	5.4	5.4	5.4
Average X-slope (%)	1.70	1.70	1.70
Trail Condition Information			
Deferred Maintenance	\$455		
CRV	\$16,699	\$7,422	\$16,699
FCI	0.02	0.00	0.00
Condition	Good	Excellent	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$455	\$40,820	0.00	Excellent

TRAIL DEFICIENCY



Trail Name: Nature Trail

Refuge Name: North Attleboro NFA

Trail Number: T200

Region: 5

Total Length: 0.74 Miles

Mile Post	0.03	0.03
Section Number	001	001
Photo Number	NOAT_C2_0007	NOAT_C2_0006
Deficiency	Drainage	Drainage
Action	Repair	Build/Add
Item	Puncheon -lf	Puncheon -lf
Quantity	25	20
Deferred Maintenance	\$186	\$269

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0004 - MP 0.00 - Sign

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0005 - MP 0.00 - Trailhead

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0007 - MP 0.03 - Puncheon -lf

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0009 - MP 0.17 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0011 - MP 0.33 - Sign

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0012 - MP 0.33 - Begin Section

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0013 - MP 0.34 - Bridge -sf

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0015 - MP 0.41 - Begin Section

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0019 - MP 0.70 - Sign

TRAIL NUMBER: T200
STATION: North Attleboro NFH
DATE: 07/28/2006



Photo # NOAT_C2_0020 - MP 0.71 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T200

STATION: North Attleboro NFH

DATE: 07/28/2006



Photo # NOAT_C2_0002 - MP 0.73 - Sign

TRAIL NUMBER: T200

STATION: North Attleboro NFH

DATE: 07/28/2006



Photo # NOAT_C2_0021 - MP 0.73 - Bridge -sf

Glossary of Terms and Abbreviations

Acc Info	Accessibility information available at trailhead.
Action	Action required to correct deficiency.
Admin Road	Administration Road. Admin Roads signed and advertised as trails are included in the trail inventory but a condition assessment is NOT done.
Alt SAMMS	SAMMS number of Alternate Facility Type.
Alt Type	Alternate Facility Type. Trail lies on a feature such as a levee, dam, administrative road or bridge, which has a separate SAMMS number.
AvgGrade	The average grade of the trail (%). The average of five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.
AvgSlope	The average cross-slope of the trail (%). The average of five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.
Check Dam	A small dam constructed across a drainage ditch, swale, or channel to lower the speed of concentrated flows.
Condition	Subjective rating of trail based on Facility Condition Index (FCI): FCI \leq .01 = Excellent FCI .02 - .05 = Good FCI .06 - .10 = Fair FCI .11 - .20 = Poor FCI $>$.20 = Failed
Crib Wall	Retaining wall.
Current Replacement Value (CRV)	The value of an asset determined by the estimated cost of replacing it.
Def type	Deficiency Type: Trail Structure, Drainage, Erosion, Obstacle, Trail Location, Other.
Deferred Maintenance (DM)	Maintenance that was not performed when scheduled.

Elem ID	Unique identifier for each trail section: Org Code-Trail Number-Section Number.
Facility Condition Index (FCI)	DM/CRV
Grouped Features	Grouped features include non-unique signs (mileposts, interpretive signs, species identification, etc.), water bars, check dams, steps, drain and drainage dips. For any given grouped feature, a GPS point and photo are taken for the first occurrence only and the total number of features in the group are entered into the “quantity” field of the data dictionary.
Info Type	Type of accessibility information available at trailhead: brochure, sign or other.
Item	Item on which the “Action” (see above) will be performed.
Manage_Use	Managed use of the trail: HIKE, BIKE, NSPC (non-specified), PACK, POR (portage), SNOWSHOE, XSKI (cross-country ski), OTHER.
MP	Distance of a trail feature or deficiency from the Trailhead.
Puncheon	Log footbridge used in area of poor drainage.
Raised Trail Structure	Boardwalk, Turnpike, Puncheon.
T Class	Trail Class: I-V (see Appendix ? for trail class descriptions).
Tr Desig	Trail Designation: Standard (Std), National Historic Trail (NHT), National Recreation Trail (NRT), National Scenic Trail (NST).
Turnpike	Trail tread elevated with dirt, rock or other aggregate from parallel side ditches and held in place by logs.